Annexure (BOQ)

Name of work : Estimate for repairing of broken reinforced concrete sunshades (south side) of upper floors of the Bijulee Bhawan building.

: AEGCL/MD/BBM/Repairing & Renovation works/2024/01/168 Dated:- 03/01/2026

	10			9 8			7					6			
	New work (Two or more coats applied @ 1.43 litre/ 10 sqm. Over and including priming coat of exterior primer applied @ 1.90 litre/10 sqm.	15489:2004,Alkali & fungal resistance, dirt resistance exterior paint of required shade (Company Depot Tinted) with silicon additives.	Finishing walls with 100% Premium acrylic amultion point by	plastered wall surface to prepare the surface even and smooth complete.	12 mm average thickness.	graded coarse sand with polymer minimum 2% by wt. of cement used) as per specifications and directions of Engineer-in-	Providing, mixing and applying SBR polymer (of approved make) modified Cement mortar in proportion of 1.4 (1	75mm thick in Grade M 25 with cement content not less than 330 kg per cum	portland cement, coarse sand and graded stone aggregate of 10mm maximum size in proportion as per design criteria] with specified average thickness.	nlain/reinforced coment concepts for attention approved make @ minimum 2% by wt. of cement used) modified	Providing mixing and applying SBB polymor/of	with specified proportion of approved polymer	direction of Engineer-In-charge complete in all respect.	Providing, mixing and applying bonding coat of approved adhesive on chinned portion of BCC	
60.000			60.000	000	60.000		75.000				35.000		i		
Sqm			Sam	Jahr			Sqm				Sam				

in words:

(A) Sub Total = Rs.
(B) Add 18% GST on (A) = Rs.
(C) Grand Total(A+B) = Rs.
Say = Rs.